



AVIA PROPELLER Ltd.

Beranových 666, 199 00 Praha 9 - Letňany, Czech Republic

MADATORY BULLETIN

- Number:** V 500A/ 7a
- Refers to:** The inspection of P 7900.01 oil distributor flange on V 500A propellers exposed to aerobatic use.
- Reason:** Based on experience from the propeller operation, test results and mathematic analyses.
- Action:** Repetitive flange inspection to the extent according to Mandatory bulletin No. V 500A/6a is ordered to be done immediately. A customer shall carry out the repetitive inspection provided the flange has been and/or snap roll flight maneuvers.
- A record shall be made into a propeller logbook upon completing the reinspection.
- Costs:** Costs shall be borne by a customer.
- Bulletin effectivity:** Since the date of Bulletin approval.
- Date of approval:** April 18, 1995

J. Sviták
AHSA Engineering Manager

M. Petru
President of AHSA

P. Kulovaný
AHSA Chief Designer

I. Brunclík
AHSA Sales Manager

Jan Beneš
CAI of the CR