



**Subject : Possible Spinner Assemblies for AVIA Propellers**

PROPELLER SERIES		SPINNER ASSEMBLY		
<b>AV-723</b>	Hydraulic variable pitch propeller	091-4000 091-4006 091-4010		
<b>AV-725</b>	Hydraulic variable pitch propeller	116-4000 116-4001 116-4003	116-4004 116-4005 116-4006	
<b>AV-803</b>	Hydraulic variable pitch propeller	106-4000.1 (no longer available) 106-4000.2 106-4002 106-4003 106-4003.1		
<b>AV-804</b>	Hydraulic variable pitch propeller	117-4000		
<b>AV-842</b>	Hydraulic variable pitch propeller	093-4000		
<b>AV-843</b>	Hydraulic variable pitch propeller	101-4000 101-4007		
<b>AV-844</b>	Hydraulic variable pitch propeller	103-4000 103-4003 103-4004	103-4007 103-4010 103-4012	
<b>V210</b>	Fixed pitch propeller	054-0005		
<b>V310</b>	Ground adjustable pitch propeller	050-4000		
<b>V410</b>	Electric pitch control propeller	V410-4 V410A-4 V410A-4.1	V410AT-4 V410T-4 V410F-4	
<b>V500</b>	Hydraulic variable pitch propeller	060-4000		
<b>V503</b>	Automatic hydraulic propeller	053-4000 073-4000		
<b>V506</b>	Hydraulic variable pitch propeller	V506-4		
<b>V508</b>	Hydraulic variable pitch propeller	059-4000 059-4000.1 059-4000.2 059-4000.3 059-4000.4	059-4000.5 059-4000.6	100-4000 100-4000.1 100-4000.2 100-4000.3 100-4000.4
<b>V510</b>	Hydraulic variable pitch propeller	068-4000 068-4001 068-4002		
<b>V520</b>	Hydraulic variable pitch propeller	V520-2070		

*The technical content of this document is approved under authority of DOA No. EASA.21J.072.*

Office of Airworthiness Zbyněk Tvrdík  Date: February 14, 2019	Prepared Michal Rout  Date: February 14, 2019		Page : 1 Pages : 1
---	--	--	-----------------------